


DAIMLERCHRYSLER

DaimlerChrysler
India Private Limited

Pune, October 22, 2003

Kind Attention - Workshop Managers :

- ✓ Cama Motors, Ahmedabad
- Sundaram Motors, Bangalore
- Interkraft, Kolkata
- Tai-Pan Traders, Chandigarh
- Trans Cars, Chennai
- T & T Motors, New Delhi
- Adishwar Auto, Hyderabad
- Sanghi Motorcar Co., Mumbai
- Auto Hangar, Mumbai
- Millennium Motors, Pune
- Patel Auto Services
- Sundaram Motors, Chennai



Service Measure – Check for cover for air inlet slot and replace if necessary Model W 220 and W 215

Dear All,

We are in receipt of a subject service measure from DCAG. The details of the vehicles in your responsibility is attached herewith. The vehicles where the concerned dealer could not be identified are also included in the list. If such a vehicle reports to your dealership, then please carryout this action otherwise provide us a written confirmation that the vehicle does not report to your workshop.

As per the details received from DCAG, on the above mentioned vehicles a cover under air inlet slot of the hood may not have been installed. Please check whether this cover has been installed on the vehicle's next visit to workshop. If this is not the case, please retrofit a cover, as per the work instruction attached herewith.

Operation texts and flat rates:

| <u>Operation no.</u> | <u>Flat rate</u> | <u>Operation text</u> |
|----------------------|------------------|--|
| 02 – 3945 | 0.3 Hrs | Check for cover for air inlet slot and replace if necessary. |

Cont.....2

DaimlerChrysler India Private Limited. Registered Office, Corporate Office & Works: Sector 15-A, Chikhali Village, Pimpri, Pune 411 018 (India)
Phone: (+91) 20 7470810

Fa: Managing Director & CEO: (+91) 20 7477257, Marketing: (+91) 20 7478222, Production: (+91) 20 7478780, Finance and Controlling (+91) 20 7478748,
Corporate Affairs: (+91) 20 7473597, Human Resources: (+91) 20 7473618



: 2 :

| <u>Parts description</u> | <u>Part no.</u> | <u>Qty. per vehicle</u> |
|----------------------------|---------------------------|-------------------------|
| Cover for right-hand drive | <u>A 220 880 07 05 05</u> | 01 |

Damage code

0 88920457

A warranty/goodwill claim for the costs of labour and material (if any) may be submitted to us, quoting the accounting number 8892045.

This service measure should be completed by the end of October 2004.

Please acknowledge receipt of this letter and feel free to contact us if you have any queries.

With best regards,

DaimlerChrysler India Private Limited



D. Chandavarkar
Divisional Manager
Field Service



Devendra Thakur
Sr. Manager
Customer Service

Encl. - Work Instruction
- Vehicle List

Work description for service measure at next workshop stay

Check cover under air inlet slits and exchange if necessary

Model W 215/220 RHD


Procedure

1. Check to see if the correct cover has been installed (see FIGURE 1 for incorrect cover).
2. Open engine hood as described in AR88.40-P-1000M (vertical position).
3. Check to see if the correct cover has been installed in the engine hood (closed cover must be on top of the brake fluid reservoir) (see FIGURE 1). If the open side of the cover is present on top of the brake fluid reservoir, the cover must be exchanged.
4. Remove/install the cover as described under item 5 in AR 88.40-P-3000M.

Parts

| Qty. | Description | Part number |
|------|-------------|-----------------|
| 1 | Cover, RHD | A 220 880 07 05 |
| 05 | | |

FIGURE 1



Operation texts and flat rates

| <u>Operation number</u> | <u>Operation text</u> | <u>Flat rate</u> |
|-------------------------|--|------------------|
| 02-3945 | Check air inlet slits cover and replace if necessary | 0.3 h |

DaimlerChrysler AG
Global Service & Parts