

Only one car
in list which does
not belong to our territory
List attached
duy
79/10/04

DAIMLERCHRYSLER

DaimlerChrysler
India Private Limited

Pune, October 12, 2004

All Workshop Incharge
DC India dealerships / ASC

Service Measure – Check turn signal indicator socket, replace if necessary.
Model 211

Dear All,

We are in receipt of a subject Service Measure from DCAG. Enclosed please find the Work Instructions for carrying out the subject activity. Only one vehicle is to be attended for this activity. The vehicle details are given in the enclosed CD. Please perform this measure during the vehicle's next visit to the workshop and inform us accordingly. The work instructions are attached for your reference.

Operation texts and flat rates:

<u>Operation no.</u>	<u>Flat rate</u>	<u>Operation Text</u>
02-4440	0.1h	Check turn signal sockets (after quick test)
02-4385	0.2h	Replace turn signal indicator socket (after inspection)

Parts:

Part Designation	Part No.	Quantity
Turn signal indicator socket	A 001 826 19 82 05	2
Turn signal indicator socket	A 001 826 35 82 05	2

Damage Code: 082 910 347 (in case of repairs with part replacement)
082 910 348 (in case of repairs without any part replacement)

Cont.....2

Board of Management :
Dr. Klaus-Peter Arnold, Piyush Arora, Hans-Michael Huber (Speaker),
Suhas Kadlaskar, Rolf Löffler, Augustus Mallier, Sanjiv Sahajwala

A Company of the DaimlerChrysler Group

Registered office, Corporate Office & Works
Sector 15-A, Chikhali
Pimpri, Pune 411 018 (India)
Phone: (+91) 20 27505000
www.mercedes-benz.co.in

: 2 :

Cost Settlement:

A warranty/goodwill claim for the costs of labor and material (if any) may be submitted to us quoting the **accounting number 82 910 34**.

Completion Deadline:

The above campaign should be completed by **30th April 2005**.

Please acknowledge receipt of this letter and feel free to revert to us for any queries.

Thanking you,

With best regards,
DaimlerChrysler India Private Limited



D. Chandavarkar
General Manager
Aftersales



Ashish Salvi
Divisional Manager
Field Service

Copy to - DCIPL Service Representatives] for close follow up with the workshops

Encl. - Work Instructions
- CD containing vehicle list

Code: 0404P82A43

Work description

Check turn signal indicator socket, replace if necessary
Model 211

Test Procedure

1. Open engine hood and check whether turn signal socket has been repaired as per AF 82.10-P-2014C with repair kit (A203 826 01 82 /02 82). If not then replace turn signal socket according to following procedure.

Procedure

2. Remove turn signal indicator socket.
3. Insert bulbs (turn signal lamps) into the new sockets.
4. Install new turn signal indicator socket.

Parts

Number	Designation	Part no.
2	Turn signal indicator socket	A 001 826 19 82 05
2	Turn signal indicator socket (USA version)	A 001 826 35 82 05

Operation text and flat rate

Operation no.	Flat rate	Accounting no.
Check turn signal sockets (after quick test) 02-4440	0.1 h	82 910 34
Replace turn signal indicator socket (after inspection) 02-4385	0.2 h	82 910 34

DaimlerChrysler AG
Global Service & Parts