

83.00-P-0005A	Service Information: Replacement of blower motor and blower regulator	11.8.08
---------------	---	---------

MODEL 211.### #B up to 081230,
219.### #A up to 098501

i To avoid any follow-up repairs, for all work in which the blower motor or blower regulator have to be replaced, both components have to be replaced together.

The exact method is described in the TIPS system in Group 83.00 under the title "Blower switches off without obvious cause". Operations without a TIPS connection should contact the responsible MPC.

i Replacing the control panel does not rectify the problem.