

Service Measure - Check water drain grommet in front wheel house on driver and front passenger sides and remove if necessary

Sr. No.	Chassi No.	Customer Name	Completion Status
1	WDB2110066A150308	Does Not Belong to our territory	
✓ 2	WDB2110066A192422	Kishore Ranmal Godhania	GJ3 AB 9929 <i>any</i>
3	WDB2110066A192446	Does Not Belong to our territory	
✓ 4	WDB2110066A192461	Jivabhai Parmar	GJ3 AB 6010 <i>any</i>
✓ 5	WDB2110066A237969	Prakash Barmecha	GJ2L 5U01 <i>any 17-2-05</i>
✓ 6	WDB2110066A280354	Essen Multipack	GJHS 5051 <i>any</i>
✓ 7	WDB2110066A332950	Pandit S. Shukla	GJ6 BA 02 <i>any</i>
✓ 8	WDB2110066A332960	K.S. Motors	474 - New Car <i>any</i>
✓ 9	WDB2110066A332968	Devraj R. Agarwal	GJ1HG 6906 <i>any</i>
✓ 10	WDB2110616A105298	Surendra Nath Kapoor	405 - <i>any</i>
✓ 11	WDB2110616A105299	Dilip K. Mehta	GJ1HD 2366 - <i>any</i>
✓ 12	WDB2110616A105322	Dhami Brothers	GJ5CA 6565 <i>any</i>
✓ 13	WDB2110616A105330	Somani Fab Pvt. Ltd.	466 <i>any</i>
✓ 14	WDB2110616A105368	Rajendra Shukla	GJ1HE 1101 <i>any 28-4</i>
✓ 15	WDB2110616A105373	K.P. Sanghvi & Sens.	GJ5CA 9889 <i>any</i>
16	WDB2110616A177959	Does Not Belong to our territory	
✓ 17	WDB2110616A217015	Schmetz India Pvt. Ltd.	GJ22J 3344 <i>any</i>
✓ 18	WDB2110616A217022	Bayer ABS Ltd.	GJ6AH 8600 <i>any</i>
✓ 19	WDB2110616A237997	Dr. Firoz Holia	GJ6AH 8998 <i>any</i>
✓ 20	WDB2110616A280446	Dr. Vikram Shah	GJ1HB 5986 <i>any</i>
✓ 21	WDB2110616A332978	Goldy Projects	GJ6BA 9999 <i>any</i>
✓ 22	WDB2110616A333012	Venus Jewel	GJ5CB 9939 <i>any</i>
✓ 23	WDB2110616A333023	Balaji Wafers	GJ3AB 8960 <i>any 10-3-05</i>

Buntibhu Feb. done

Jayesh Thakkar 10-1-05