

DAIMLER

Service measure
Replace upper guide pulley for V-belt

Mercedes-Benz India
Aftersales

Sr. No.	Chassis No.	Comm. No.	Model	Location	Completion Status
✓ 71	WDD2110546L002384	0682591154	E 280	Cama Motors Pvt. Ltd.	Rajesh Balwadhra's Rangan
72	WDD2211712A052086	0682510053	S 500	Cama Motors Pvt. Ltd.	Akshayprashantam
73	WDD2110546L002380	0682591150	E 280	Cama Motors, Ahmedabad	Sudhir Narsarao
74	WDD2110546L002390	0682591160	E 280	Cama Motors, Ahmedabad	KHS machinery
75	WDD2110546L003577	0682591393	E 280	Cama Motors, Ahmedabad	Mehesh Vijay
76	WDD2210562A051106	0682510044	S 350	Cama Motors, Ahmedabad	Cama Hotel
77	WDB1714562F105530	0582510135	SLK 350	Cama Motors, Ahmedabad	Jayraj RV Jay
78	WDD2211566A035992	0682590042	S 350	Cama Motors, Ahmedabad	Sunder Jindal Ltd