Phoning Hardle Senst paul

101. go shrough and DA

DAIMLERCHRYSLEN attached fold to the deliver of the

India Private Limited

Pune, September 22, 2004

Kind Attention - Workshop Managers:

Service Measure - Install wiring harness with fuse holder for A.C. blower.

Model W 220 and W 215

Dear All,

It has been observed that under extreme ambient conditions, e.g. vehicle's engine at idle speed. high outside temperatures and blower at maximum setting, the temperature at the fuse for the blower regulator could increase in isolated cases. Hence please install a wiring harness with a fuse holder (Part No. A 220 540 95 07 05) in to these vehicles during next workshop visit.

The details of the vehicles in your responsibility is attached herewith. The vehicles where the concerned dealer could not be identified are also included in the list. If such a vehicle reports to your dealership, then please carryout this action otherwise provide us a written confirmation that: the vehicle does not report to your workshop.

Please refer WIS document no. AN83.10-P0001M for work instructions. Please note that the procedure in AN83.10-P-0001-01MN must be changed as of step 5:

Step 5: Unpin the red/yellow wire from the brown fuse carrier and cut off wire lug.

Step 6: Omitted

Step 7: Cut off plug from wiring harness A 220 540 95 07.05 and solder to unpinned red/yellow wire from step 5. Afterwards, insulate wire with heat-shrink wrapping.

Perform the rest of the tests

Operation texts and flat rates:

Operation no.

Operation text

02 - 4340/01

1.9 Hrs

Install wiring harness for interior Now

DaimlerChrysler India Private Limited. Registered Office, Corporate Office & Works: Sector nikhali Village, Pimpri, Pune 411 018 (India) Phone: (+91) 20 7470810

Fax: Managing Director & CEO: (+91) 20 7477257, Marketing: (+91) 20 7478222, Production: (+91) 20 7478780, Finance and Controlling (+91) 20

Damage code
0 83 900 32 7

A warranty/goodwill claim for the costs of labour and material may be submitted to us, quoting the accounting number 83 900 32.

This service measure should be completed by 31 December 2005.

Please advise your concerned staff accordingly and ensure availability of the wiring harness in your stock.

Please acknowledge receipt of this letter and feel free to contact us if you have any queries.

With best regards,

DaimlerChrysler India Private Limited

Å. Faria

General Manager

Aftersales

Devendra Thakur

Sr. Manager

Customer Service

Encl. _ Vehicle List

27/4/04

199/04

adalon