DaimlerChrysler

DaimlerChrysler India Private Limited

Pune, October 12, 2004

All Workshop Incharge DC India dealerships / ASC

Service Measure - Check navigation DVD and replace if necessary. Model 211 with SA code 527

Dear All,

We are in receipt of a Service Measure from DCAG on checking navigation DVD and replacing the same if required. The related Work Instructions are enclosed herewith. Please perform this activity on the vehicles mentioned in the CD, during their next visit to the workshop.

# Operation texts and flat rates:

Operation no.	Flat rate	Operation Text
02-4383	0.1h	Check navigation DVD and replace if necessary (after quick test)

#### Parts:

Quantity Part No. Part Designation 1 Q 211 827 52 59 05 Navigation DVD

Damage Code: 082 980 457(in case of repairs with part replacement)

082 980 458(in case of repairs without any part replacement)

# **Cost Settlement:**

A warranty/goodwill claim for the costs of labour and material (if any) may be submitted to us, quoting the accounting number 82 960 45.

Cont....2

Board of Management: Dr. Klaus-Peter Arnold, Piyush Arora, Hans-Michael Huber (Speaker), Suhas Kadlaskar, Rolf Löffler, Augustus Mallier, Sanjiv Sahajwala

Registered office, Corporate Office & Works Sector 15-A, Chikhali Pimpri, Pune 411 018 (India) Phone: (+91) 20 27505000 www.mercedes-benz.co.in

A Company of the DaimlerChrysler Group

## **Completion Deadline:**

The above campaign should be completed by 30th April 2005.

Please acknowledge receipt of this letter and feel free to revert to us for any queries.

Thanking you,

With best regards, DaimlerChrysler India Private Limited

D. Chandavarkar General Manager Aftersales

Ashish Salvi Divisional Manager

Field Service

Copy to - DCIPL Service Representatives ) for close follow up with the workshops

Encl. - Work Instruction and

- CD containing vehicle list

Pimpri, Pune 411 018 (India) Phone: (+91) 20 27505000 www.mercedes-benz.co.in

## Code: 0404P82A48

# Check navigation DVD and replace if necessary Model 211 with SA code 527

### **Testing Procedure**

 Check SW status in navigation computer. SW must be at least 07/04 otherwise replace NAVI DVD.

#### Procedure

- 2. Insert new navigation DVD into navigation computer in luggage compartment.
- 3. Ensure that you observe AF82.85-P-6069A and AF82.85-P-6067A.

#### **Parts**

Quantity	Designation		Part no.		
1	Navigation DVD	Q 211 827 52 59 05			
Operation text and flat rate					
Operation no.		Flat rate	Accounting no.		
Check navigation DVD and replace if necessary (after quick test) 02-4383 0.1 h 82 980 45					

DaimlerChrysler AG Global Service & Parts