

DaimlerChrysler India Private Limited

Pune, September 30, 2005

All Workshop Incharge DC India dealerships / ASC

Suppliment to Service Measure - Replace battery Model 203, right-hand drive vehicles (Accounting No. 5490049)

Dear All,

Kindly refer our earlier document dated 30<sup>th</sup> March 2005 related to the above mentioned Service Measure. The work instruction for this Service Measure has been revised. The same is enclosed herewith for your reference. Please note that as per the revised work instructions, the battery should be replaced **only if** the make of battery fitted in the vehicle is **FNB** (**First National Battery**).

Kindly ensure that your concerned staff is well aware of the above. For any queries you may have related to this information, please immediately contact the right undersigned or Mr. Devendra Thakur.

Please acknowledge receipt of this letter.

With best regards, DaimlerChrysler India Private Limited

D. Chandavarkar

Director

After-Sales

Ashish Salvi

Dy. General Manager

Field Service

Copies to - DCIPL Service Representatives} for information.

Encl. - Revised Work Instructions (Annexure I)

Board of Management: Klaus-Peter Arnold, Piyush Arora, Hans-Michael Huber (Speaker), Ravi Gogia, Suhas Kadlaskar, Augustus Mallier, Sanjik Sahajwala

A Company of the CalmierChrysler Group

On destruction of the construction of the cons

Registered office, Corporate Office & Works Dr. Sector 15-4, Chil hali

Pimpri, Pune 411 018 (India) Phone: (\*91) 20 27505000 www.mercedi.sateria.com

## (Annexure I)

## WORK DESCRIPTION FOR SERVICE MEASURE

Code: 203-BATAUS Version: 1.0

Check battery, replace if necessary Model 203, right-hand drive vehicle

## Check/test procedure

- 1. Open engine hood.
- 2. Remove dust filter housing.
- 3. Check make of battery.

  For FNB (First National Battery) proceed with work steps, otherwise end measure.

## Work procedure

- 1. Replace battery. (AR 54.10-P-0005P)
- 2. Install in the reverse order.

Parts			
Quantity	Designation		Part no.
As required	Battery 62 Ah		A 005 541 23 01 26
As required	Battery 74 Ah		A 005 541 24 01 26
As required	Battery 100 Ah		A 005 541 25 01 26
Operation to	ext and flat rate		
Operation no	. Operation text	Flat rate	Accounting no.
02-3809	Replace battery	0.5 hrs.	54 900 49

DaimlerChrysler AG Global Service & Parts