

Service Information

Distribution : Dealers + Service Stations
MBIL Field Service Rep.

X
X

28 September, 2000

S. I. No. - IND 58/001

 Passenger Car

Applicable to : W 220

Production number sticker in the Trunk and on the right side 'A' pillar


It has been observed that the above mentioned stickers were wrongly fixed on some vehicles. The enclosed list shows the affected vehicles, which were dispatched to you.

We are also enclosing herewith the correct stickers to be fixed on the respective vehicles (Please refer the list). The exact locations of these stickers are shown in the attached pictures.


If the vehicles are not yet delivered to the Customers, we request you to carry out this job immediately. For the delivered vehicles, please complete this job during the next visit to the workshop.

Please acknowledge receipt of this Service Information and kindly send us the completion reports as soon as the jobs are completed.

With best regards,
Mercedes-Benz India Limited.



O. Oliveira
General Manager
Aftersales



D. Chandavarkar
Divisional Manager
Field Service

Encl - As above

